

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Assistant Engineer)

((Ref: G.O. Ms. 20/70/PWD dt. 23/01/1970))

1. Name of the Officer : ASHA DEVI
2. Name of the School : PARAMA BHATTARA KENDRIYA VIDYALAYAM
3. Location with name of Education District / Sub. District : Vadayampady| Aluva | Kolenchery/
4. Classification of Building as specified in column 4 of the application for fitness certificate and size : Permanent buildings (Dimensions in metres)
G+2 plinth area
1. 79.16x8.44x3.60-3 nos(Ground floor,First floor,Second floor)
2. 41.40x8.09x3.60-3 nos(Ground floor,First floor,Second floor)
3. 9.65x3.85x3.60-3nos(Ground floor,First floor,Second floor)
4. 27.62x8.68x3.60-3nos(Ground floor,First floor,Second floor)
5. Period for which the certificate is issued : 2023-2024
6. Nature of defects, if any : }
i. Foundation and basement
ii. Superstructure
iii. Doors and Windows
iv. Wood work wrought and put up
v. Roof
vi. Flooring
vii. Miscellaneous (Cracks, etc.) } Nil
7. Any major defects noticed which will render the building unsafe in any manner : No
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes : Sound under normal weather conditions

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood, etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

No.: 12/AE/AKD/FT/2023-24

CERTIFICATE

Certified that the buildings of PARAMA BHATTARA KENDRIYA VIDYALAYAM, Kolenchery were inspected by me on 08/08/2023 and found to be fit to conduct classes for the period 2023-2024 under normal natural weather conditions for the reasons stated above.

Place: Kadayiruppu

Date: 08/08/2023



(Seal)

ASHA DEVI
ASSISTANT ENGINEER
LSGD SECTION
AKKARANADU GRAMA PANCHAYAT
KADAYIRUPPU